GROB Luft- und RaumfahrtASB315-63/2Lettenbachstrasse 9Page 1 of 4D-86874 Tussenhausen-Mattsies02 June 2003This Service Bulletin supercedes ASB 315-63 dated 29 May 2003

# ALERT SERVICE BULLETIN NO. ASB315-63/2

# I. TECHNICAL DETAILS

# 1.1 Category:

ALERT

# 1.2 Airplanes affected:

G 103 TWIN II

G 103A TWIN II ACRO G 103C TWIN III ACRO S/N 3501 – 3729 S/N 3730 – 3878 S/N 33879 – 34078 S/N 3544 – 34078 (mit Suffix "K") S/N 34101 – 34203

# 1.3 Time of Compliance:

Prior to next flight

# 1.4 Subject:

ATA-Code:

**Limitation of Operation** 

# 1.5 Reason:

New investigations of the fuselage structure have indicated, that the safety margins against damage of the fuselage structure under limit loads might be insufficient. Therefore, the speeds for rough air  $v_B$  and the maximum flying speed  $v_{NE}$  and further speeds as a consequence are reduced, as given in para 1.8, until the investigations are finished or corrective actions, if required, were accomplished.

Aerobatic flights are provisionally prohibited as a consequence of the reduced speeds. GROB will complete the investigation at short notice and, if necessary, corrective actions will be issued as soon as possible.

# **1.6 Concurrent documents:**

None

G 103A G 103B G 103C



GROB Luft- und RaumfahrtASB315-63/2Lettenbachstrasse 9Page 2 of 4D-86874 Tussenhausen-Mattsies02 June 2003This Service Bulletin supercedes ASB 315-63 dated 29 May 2003

## 1.7 Approval Note:


The technical information contained in this document has been approved under the authority of JAA Design Organization Approval No. LBA.NJA.008.

#### **1.8 Accomplishment/ Instructions**

- 1.8.1 Apply on the front and rear airspeed indicator
  - a red mark at 230 km/h (124,2 kts, / 142,9 mph)
  - a yellow mark at 167 km/h (90,2 kts, / 103,8 mph)

NOTE: The marks are attached to the SB.


1.8.2 Apply the following red placard (according to airspeed indicator calibration) to the front and rear airspeed indicator:





1.8.3 Apply the following red placard close to the front and rear airspeed indicator (refer to figure on page 2):

NOTE: ONLY APPLICABLE FOR AEROBATIC APPROVED GLIDER !



1.8.4 Apply the following limitation placard over the existing placard on the front and rear RH cockpit side wall:

### For G 103 TWIN II and G 103A TWIN II ACRO:

Maximum flying weight			580 kg / 1280 lbs		
Maximum airspeeds:		km/h	kts	mph	
in calm air:	$V_{NE}$	230	124,2	142,9	
in rough air:	VB	167	90,2	103,8	
aerotow:	V <sub>T</sub>	167	90,2	103,8	
winch or auto tow:	Vw	120	64,8	74,5	
airbrakes extended:	$V_{FE}$	230	124,2	142,9	
manoeuvering speed:	VA	167	90,2	103,8	

#### For G 103C TWIN III ACRO:

Maximum flying weight 600 kg / 1323 lb				
Maximum airspeeds:		km/h	kts	mph
in calm air:	V <sub>NE</sub>	230	124,2	142,9
in rough air:	VB	167	90,2	103,8
aerotow:	V <sub>T</sub>	167	90,2	103,8
winch or auto tow:	Vw	140	76	87
airbrakes extended:	$V_{FE}$	230	124,2	142,9
manoeuvering speed:	VA	167	90,2	103,8

#### **1.9 Repetitive Actions**

None

G 103A G 103B G 103C

## 1.10 Mass (Weight) and CG:

N/A

# **II. PLANNING INFORMATION**

#### 2.1 Material & Availability:

The red and yellow mark and the placards (gty. 2 each) are attached to the SB.

#### 2.2 Special Tools:

N/A

#### 2.3 Labour costs:

approx. 10 min.

#### 2.4 Reference documents:

N/A

#### 2.6 Credit:

N/A

# **III. REMARKS**

- 3.1 The correct execution of the instructions may be performed by a competent person and has to be certified in the logbook by an authorised inspector.
- 3.2 If you have sold your aircraft in the meantime, would you kindly pass this information on to the new owner and forward his address and aircraft S/N to us.
- 3.3 For questions and assistance please contact:

Rudi Vodermeier, Head of Product Support, phone: +49 8268 998139 fax:

+49 8268 998200

productsupport@grob-aerospace.de e-mail:

> G 103A G 103B G 103C