



Technical Information

TM 315 - 15

TWIN ASTIR
TWIN ASTIR
TRAINER

Subject: Increase of Service Time.

Effectivity: Sailplanes TWIN ASTIR and TWIN ASTIR TRAINER, all serial numbers.

Accomplishment: Before reaching a service time of 3000 hours but not later than December 31, 1981.

Reason: The results of fatigue tests of wingspar sections have demonstrated recently that the service time of FRP gliders and motorgliders may be extended to 6000 hours, if for each individual glider (in addition to the obligatory annual inspections) the airworthiness is demonstrated according to a special multi-step inspection program particularly with regard to the service life.

Instructions: Complete the Maintenance Handbook with the section XI. "Inspection Procedure for increase of service time" (Page 23).
More-over change the pages 1 and 2.

Material: Page 1, 2 and 23 dated September 30, 1981 for Maintenance Handbook.

Remarks:. The proper execution of this technical information must be certified by a competent authority in the aircraft logbook.

Mattsies, September 30, 1981

gez. i. A. Dipl. Ing. H. Wilser

Wilser

LBA acknowledged:

9. 11. 81