

## Service Bulletin TM 315-39

GROB G 103 C TWIN III ACRO

Subject:

Installation of new hinged operating handle

on the air brake lever

Effectivity:

GROB G 103 C TWIN III ACRO

all s/n

Urgency:

- Aircraft, which are operating with a pre-

liminary permit to fly:

before production inspection

- Aircraft, which are already registrated:

up until 4 November 1989

- All other aircraft:

installation performed at the manufacturer

Reason:

During type certification it was recommended that this modification would greatly improve the egress from aircraft during an emergency exit. Therefore all s/n will be thus modified.

Actions:

The previous air brake lever 103C-4405.02 will

be provided with a new hinge 103C-4408.

Material:

All necessary materials/parts will be supplied

free of charge from the manufacturer.

Weight and Balance: No effect

Remarks:

Installation can be carried out by a competent

person according to installation instructions

No. 315-39.

The proper execution has to be certified in the log-book by an authorized inspector, and a confirmation sheet (copy attached) comple-

ted and returned to the manufacturer.

Mattsies, 13 June 1989

LBA approved

The German original of this service bulletin has been approved by the LBA under the date of 29 June 1989 and is signed by Mr. A. Skov. The translation has been done by best knowledge and judgement. In any case of doubt, the German original is authoritative.

Me

signed i.A. R. Rischer
(Airworthiness engineer
certification staff)

P.S.: In case you have sold your glider meanwhile, we ask you kindly to give this information immediately to the new owner and to let us know his address and serial number.

Datum 13 June 1989	ersetzt Ausgabe vom	Bearbeitung J. Altmann	Musterprüfer	Seite 1 of 1