



Service Bulletin
TM 315-41

GROB
G 103 C TWIN
III ACRO

Subject: Substitution of slaving guide and spindle in rudder pedal unit.

Concerning: GROB G 103 C TWIN III ACRO all serial numbers, except those already equipped. (refer to list, page 2)

Urgency: Next annual inspection

Procedure: Supplier used wrong material for manufacture of slaving guide and spindle. As precautionary measure those parts have to be replaced by new ones.

Actions: Remove, mark, respectively destroy present slaving guide and spindle and replace them by new parts.

Material: Material necessary for SB can be obtained from manufacturer free of charge.


Weight and Balance: No influence

Remarks: Installation can be carried out by an expert according to Installation Instruction No. 315-41. Correct execution is to be certified into logbook by an authorized inspector.

Mattsies, 28 Sept 1989

LBA approved

The German original of this service bulletin has been approved by the LBA on the 09 Oct. 1989 and is signed by Mr. *SKO.V.*
The translation has been accomplished to our best knowledge and judgement. In case of doubt, the German original is authoritative.


signed i.A. R. Rischer
(Airworthiness engineer
certification staff)

P.S.: In case you have meanwhile sold your glider, we ask you kindly to forward this information immediately to the new owner and let us know his address and s/n of his aircraft.

Datum
28 Sept 1989

ersetzt Ausgabe
vom

Bearbeitung
Ch. Jütte

Musterprüfer

Seite
1 of 2



Service Bulletin
TM 315-41

GROB
G 103 C TWIN
III ACRO

For the following aircraft, TM 315-41 has already been carried out by the manufacturer:

s/n : 34101, 34108, 34111, 34113, 34115,
34134, 34138, 34140,

and all aircraft as of

s/n : 34142

Datum
28 Sept 1989

ersetzt Ausgabe
vom

Bearbeitung
Ch. Jütte

Musterprüfer

Seite 2