

Subject: Revision of the maintenance manual

Concerned: G 103 C TWIN III, S/N's 36001 to 36014

Urgency: before 31 May 1992

Procedure: A revision of the maintenance manual is required for the inclusion of corrections and additional information.

Actions: The following pages must be replaced:
(Date of revision: 1/ 15.01.92)

- Wartungshandbuch (German Issue): pages 0.1, 0.2, 0.3, 8.1, 8.2, 9.3
- Maintenance Manual (English Issue): pages 0.1, 0.2, 0.3, 0.4, 0.6, 9.3, 11.1, 11.2, A 1.1, A 1.2, A 1.3, A 1.5, A 2.1, A 5.1 - A 5.14

Weight and Balance: not concerned


Remarks:

1. The revision must be carried out by a competent person and certified in the log book by an authorized inspector.
2. If you have sold your sailplane in the meantime, would you kindly pass this information on to the new owner and forward his name and address and aircraft s/n to us.


Mattsies, 15 January 1992

LBA approved

This Service Bulletin was originally written in German and approved by the German LBA on the 26 March 1992 and is signed by Mr. U. Kopp. The translation has been accomplished to best of our knowledge and judgement. In case of doubt, the German original is authoritative.


Dipl. Ing. J. Altmann
(Airworthiness engineer
certification staff)




26. März 1992